
Well and Boring Report Requirements



Marisue Crystal, Environmental Health Tech

REPORTING REQUIREMENTS


- The state of California's reporting requirements are based on the State Water Code.
- DEH reporting requirements are also based on State Water Code
 - County Code of Regulatory Ordinance
 - SAM Manual


Section 67.447 of the County Code

- A detailed record of the boundaries, character size, distribution and color of all lithologic units penetrated.
 - Type of well casing.
 - Location of perforations and sealing zones.
 - Any other data deemed necessary by the Director of the Department of Environmental Health.

Well Log Submissions 4.a.2.

- A detailed plot plan drawn to scale showing location of site and <u>nearest</u> <u>cross streets</u>
- property boundary lines, existing improvements such as USTs, piping, and/or utilities
- location of all wells and borings, both existing and proposed.





Well Log Submissions 4.a.4.

- A detailed "as-built" well construction diagram
- type of casing, screened interval, screen slot size, type of filter pack
- location and type of seals, and quantities of materials used
- surveyed well elevations and locations. Surveying must be performed by an appropriately licensed professional and meet the accuracy requirements of CCR Title 12, Section 2729-2729.1.

Date Drilled:	Date Drafted:	Dri	III Rig/Sam	pling Meth	od:		Borehole Dia.:	Casing Dia.:	Total Depth:		
3/6/02 3/15/02		2	CI	ME-75/N	lo sar	mpling conducted	10"	4"	30'	Sales and the sa	
SAN	IPLE LOG	E LOG BOREHOLE LOG					Well				
	results TPH /diesel (ppm) (N/A)	Blows per foot (N/A)	Depth (feet)	USCS symbol	Graphic	Geologic Description: Formation, soil type, color, grain, minor soil compor density, odor, etc.			nent, moisture,		
			0 1 2 3 4 5 6 7	sc	С	0-6 inches concrete. FILL 1-5 feet below grade Red-brown clay with some silt, loose, no odor. WEATHERED GRANITIC ROC 6-7 feet below grade		graded,		Bentonite grout	
			8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30	sw		Sand, fine to medium-grained. 10 feet below grade Silty clay, (60% clay, 40% silt), 11 feet below grade Some medium to coarse-grains subrounded pebbles, slightly m 15 feet below grade Sand, medium to very coarse- and pebbles, brown, poorly gra 17 feet below grade Silty clay, slightly moist. 20 feet below grade Sand, medium-grained with so coarse-grained granules, slight 22 feet below grade Sand, fine to coarse-grained, b 24 feet below grade Saturated 25-27 feet below grade Some weathered/decomposed	ed sand with hoist. grained with aded, slightly me silt and the silt and the silt moist. From to strong granite.	some grainoist.	nules very moist.	Sahu	
			31 32 33 34 35			installed.	•				

VOLUME OF MATERIALS

WELL NO.	SAND (ft³)	BENTONITE CHIPS (ft³)	BENTONITE GROUT (ft³)	CEMENT (ft³)
MW-1				
MW-2				

PROFESSIONAL SIGNATURES REQUIRED

. .

- The RG, CEG, RCE, or CHG is responsible for the accuracy and completeness of the logs and accompanying data
- All well construction and boring reports must have the original signature of the registered professional and/or their seal as required by the Business and Professions Code

